



**MIDDLE EAST NAVIGATION AIDS SERVICE
NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)**

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 049/2016

DATE: 23rd April 2016

S. O. P: TFN

TEXT OF WARNING

Southern Gulf: UAE – Creagh Shoal, Buoy Missing

BA Charts 3179, 2886

Isolated Danger Buoy named (R1) located on Relief Route of North Channel, SE of Creagh Shoal in position Lat 24°37.941N Long 052°47.270E is missing.

Mariners are requested to exercise caution in this area.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END TEXT OF WARNING

Col: 049/2016, 23, 2016, 3179, 2886, 1, 24, 37.941, 052, 47.270

MENAS is an ISO 9001:2008 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: ++973 17828541 Fax: ++973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org