



## MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

### NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 303/2024

DATE: 24<sup>th</sup> December 2024

S. O. P: TFN.

*TEXT OF WARNING*

#### **Southern Gulf: UAE – Creagh Shoal Buoy Missing.**

BA Chart: 3178, 2889

Creagh Shoal Buoy at location 24-43.20N, 052-43.06E reported Missing.

Mariners are advised to navigate with caution.

**Issuer: MENAS Maritime Operations Centre, Bahrain  
Megulite**

*END OF TEXT WARNING*

Col: 303/2024, 24, 2024, 3178, 2889, 24, 43.20, 052, 43.06.

#### **MENAS is an ISO 9001:2015 Certified Service**

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email [info@menas.com.bh](mailto:info@menas.com.bh)

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at [menas.org](http://menas.org) Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through [menas.org](http://menas.org)

**[www.menas.org](http://www.menas.org)**