



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 051/2016

DATE: 28th April 2016

S. O. P: TFN

TEXT OF WARNING

Southern Gulf: DAS Channel Buoy Re-position

BA Charts 2889, 2837, 2443, 2444, 3178, 3179

Das / Zirku Channel Buoy No.6, VQ (9) 10s is permanently moved to position 25 13.002N - 052 58.397E.

Mariners are advised to update their BA charts.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END TEXT OF WARNING

Col: 051/2016, 28, 2016, 2889, 2837, 2443, 2444, 3178, 3179, 6, 9, 10, 25, 13.002, 052, 58.397

MENAS is an ISO 9001:2000 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:
Tel: ++973 17828541 Fax: ++973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org

