



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 095/2017

DATE: 21th June 2017

S. O. P: TFN

TEXT OF WARNING

Northern Gulf: Al Basrah Approach Channel – Missing Buoys

Charts BA 1265, 2882, 2884, 2847, 2858

Lateral channel buoys at Al Basrah Approach reported missing. The charted position of the missing buoys are as the following (WGS-84):

A. Buoy No 1	29-20.90N	049-00.70E
B. Buoy No 5	29-26.50N	048-56.20E
C. Buoy No 6	29-28.30N	048-57.00E
D. Buoy No 7	29-28.88N	048-55.33E

Uncharted Buoy found in position 29-29.88N, 048-55.41E, therefore mariners are advised to navigate with caution in the channel.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END TEXT OF WARNING

Col: 095/2017, 21, 2017, 1265, 2882, 2884, 2847, 2858, 84, 1, 29, 20.90, 049, 00.70, 5, 29, 26.50, 048, 56.20, 6, 29, 28.88, 048, 55.33, 29, 29.88, 048, 55.41

MENAS is an ISO 9001:2008 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: ++973 17828541 Fax: ++973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org

