



MIDDLE EAST NAVIGATION AIDS SERVICE NOTICE TO MARINERS

NOTICE TO MARINERS

NTM: 10/2023

ISSUED DATE: 24th December 2023

Southern Gulf: UAE – Centerline Adjustments and Shifting of Dalma Buoys 1 & 2.

BA Charts: 3780, 3179.

Dalama bend Channel's boundary and centerline have been adjusted to delineate 17m depths, Dalma 1 & Dalma 2 Buoys have been shifted from their charted position to the new positions as below at the edge of new channel boundary, the width in this area is 300 Meters.

Dalma 1	24-32.159N	052-30.497E
Dalma 2	24-32.062N	052-30.676E

Mariners are requested to update their BA charts.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

Mariners are requested to inform the Middle East Navigation Aids Service, P. O. Box 66, Manama, Bahrain immediately on the discovery of new dangers, or suspected dangers to navigation and changes or defects in aids to navigation noticed in Sub-Navarea IX - Gulf and its Approaches.

MENAS is an ISO 9001:2015 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org