



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 121/2016

DATE: 13th December 2016

S. O. P: TFN

TEXT OF WARNING

Southern Gulf: UAE - Pipe Laying Operation From Mubarraz Island to Hail Island

BA Charts: 3178, 2889

Petroleum Ports Authority install Main Oil Line, Gas Injection Line, 33 KV Submarine Composite Cable and Gas Lift Line by pipe lay barge "REGINA 250" From Mubarraz Island to Hail Island in the following co-ordinates:

AA. 18" Main Oil Line x 10km:

A.	IP0	24°23.049'N	053°23.053'E
B.	IP1	24°23.055'N	053°23.042'E
C.	IP1A	24°23.062'N	053°23.046'E
D.	IP2	24°23.086'N	053°22.996'E
E.	TP1	24°23.999'N	053°22.115'E
F.	TP2	24°24.550'N	053°22.005'E
G.	TP3	24°26.227'N	053°22.700'E
H.	TP4	24°27.152'N	053°22.609'E
I.	IP3	24°27.374'N	053°22.462'E
J.	IP4	24°27.380'N	053°22.458'E
K.	IP4A	24°27.389'N	053°22.461'E
L.	IP4B	24°27.428'N	053°22.476'E
M.	IP5	24°27.437'N	053°22.481'E
N.	IP6	24°27.501'N	053°22.332'E
O.	IP7	24°27.535'N	053°22.349'E
P.	IP8	24°27.543'N	053°22.330'E
Q.	IP9	24°27.576'N	053°22.347'E
R.	IP10	24°27.582'N	053°22.333'E

BB. 6" Gas Injection Line x 10km

A.	IP0	24°27.585'N	053°22.333'E
B.	IP1	24°27.578'N	053°22.348'E
C.	IP2	24°27.544'N	053°22.331'E
D.	IP3	24°27.535'N	053°22.350'E
E.	IP4	24°27.501'N	053°22.333'E
F.	IP5	24°27.438'N	053°22.481'E
G.	IP5A	24°27.428'N	053°22.477'E

H.	IP5B	24°27.389'N	053°22.461'E
I.	IP6	24°27.381'N	053°22.459'E
J.	IP7	24°27.375'N	053°22.463'E
K.	TP1	24°27.152'N	053°22.612'E
L.	C 1	24°26.587'N	053°21.603'E
M.	TP2	24°26.203'N	053°22.709'E
N.	TP3	24°24.539'N	053°22.019'E
O.	C 2	24°24.347'N	053°22.572'E
P.	TP4	24°23.989'N	053°22.129'E
Q.	IP8	24°23.086'N	053°22.998'E
R.	IP9	24°23.062'N	053°23.047'E
S.	IP10	24°23.058'N	053°23.044'E
T.	IP11	24°23.053'N	053°23.055'E

CC. 33 KV Submarine Composite Cable x 10km:

A.	IP0	24°27.389'N	053°22.465'E
B.	IP1	24°27.379'N	053°22.462'E
C.	TP1	24°27.143'N	053°22.622'E
D.	TP2	24°26.189'N	053°22.722'E
E.	TP3	24°24.528'N	053°22.034'E
F.	TP4	24°23.979'N	053°22.143'E
G.	IP2	24°23.087'N	053°23.998'E
H.	IP3	24°23.072'N	053°23.030'E
I.	IP4	24°23.069'N	053°23.028'E

DD. 8" Gas Lift Line x 10km:

A.	IP0	24°27.588'N	053°22.334'E
B.	IP1	24°27.581'N	053°22.350'E
C.	IP2	24°27.544'N	053°22.332'E
D.	IP3	24°27.536'N	053°22.351'E
E.	IP4	24°27.501'N	053°22.334'E
F.	IP5	24°27.438'N	053°22.482'E
G.	IP5A	24°27.428'N	053°22.477'E
H.	IP5B	24°27.391'N	053°22.462'E
I.	IP6	24°27.383'N	053°22.461'E
J.	IP7	24°27.378'N	053°22.464'E
K.	TP1	24°27.133'N	053°22.631'E
L.	TP2	24°26.174'N	053°22.735'E
M.	TP3	24°24.517'N	053°22.048'E
N.	TP4	24°23.968'N	053°22.156'E
O.	IP8	24°23.084'N	053°23.002'E
P.	IP9	24°23.062'N	053°23.048'E
Q.	IP10	24°23.060'N	053°23.046'E
R.	IP11	24°23.055'N	053°23.056'E

Anchors are extended up to 600 m from the barge and Pennant Wires are connected to yellow buoy / pick up rope with Norwegian buoy, on sea surface for the anchors.

All vessels and crafts are requested to navigate with caution while transiting near the barge work zone, maintain a listening watch on VHF Channel 16 and 17, anchoring strictly prohibited in the vicinity of pipe line route, keep well clear from the barge, mariners can communicate with the barge on VHF Channel 17 and update their BA charts.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END TEXT OF WARNING

Col: 121/2016, 13, 2016, 3178, 2889, 33, 250, 18, 10, 0, 24, 23.049, 053, 23.053, 1, 24, 23.055, 053, 23.042, 1, 24, 23.062, 053, 23.046, 2, 24, 23.086, 053, 22.996, 1, 24, 23.999, 053, 22.115, 2, 24, 24.550, 053, 22.005, 3, 24, 26.227, 053, 22.700, 4, 24, 27.152, 053, 22.609, 3, 24, 27.374, 053, 22.462, 4, 24, 27.380, 053, 22.458, 4, 24, 27.389, 053, 22.461, 4, 24, 27.428, 053, 22.476, 5, 24, 27.437, 053, 22.481, 6, 24, 27.501, 053, 22.332, 7, 24, 27.535, 053, 22.349, 8, 24, 27.543, 053, 22.330, 9, 24, 27.576, 053, 22.347, 10, 24, 27.582, 053, 22.333, 6, 10, 0, 24, 27.585, 053, 22.333, 1, 24, 27.578, 053, 22.348, 2, 24, 27.544, 053, 22.331, 3, 24, 27.535, 053, 22.350, 4, 24, 27.501, 053, 22.333, 5, 24, 27.438, 053, 22.481, 5, 24, 27.428, 053, 22.477, 5, 24, 27.389, 053, 22.461, 6, 24, 27.381, 053, 22.459, 7, 24, 27.375, 053, 22.463, 1, 24, 27.152, 053, 22.612, 1, 24, 26.587, 053, 21.603, 2, 24, 26.203, 053, 22.709, 3, 24, 24.539, 053, 22.019, 2, 24, 24.347, 053, 22.572, 4, 24, 23.989, 053, 22.129, 8, 24, 23.086, 053, 22.998, 9, 24, 23.062, 053, 23.047, 10, 24, 23.058, 053, 23.044, 11, 24, 23.053, 053, 23.055, 33, 10, 0, 24, 27.389, 053, 22.465, 1, 24, 27.379, 053, 22.462, 1, 24, 27.143, 053, 22.622, 2, 24, 26.189, 053, 22.722, 3, 24, 24.528, 053, 22.034, 4, 24, 23.979, 053, 22.143, 2, 24, 23.087, 053, 23.998, 3, 24, 23.072, 053, 23.030, 4, 24, 23.069, 053, 23.028, 8, 10, 0, 24, 27.588, 053, 22.334, 1, 24, 27.581, 053, 22.350, 2, 24, 27.544, 053, 22.332, 3, 24, 27.536, 053, 22.351, 4, 24, 27.501, 053, 22.334, 5, 24, 27.438, 053, 22.482, 5, 24, 27.428, 053, 22.477, 5, 24, 27.391, 053, 22.462, 6, 24, 27.383, 053, 22.461, 7, 24, 27.378, 053, 22.464, 1, 24, 27.133, 053, 22.631, 2, 24, 26.174, 053, 22.735, 3, 24, 24.517, 053, 22.048, 4, 24, 23.968, 053, 22.156, 8, 24, 23.084, 053, 23.002, 9, 24, 23.062, 053, 23.048, 10, 24, 23.060, 053, 23.046, 11, 24, 23.055, 053, 23.056, 16, 17, 17

MENAS is an ISO 9001:2008 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: ++973 17828541 Fax: ++973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org

