



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 127/2016

DATE: 25th December 2016

S. O. P: TFN

TEXT OF WARNING

Southern Gulf: Steel Buoyancy tanks reported missing South East of Hail Island

BA Chart: 3178, 2889, 2837, 2858

Three buoyancy tanks are reported missing near Hail Island. Buoyancy tanks are made of steel, approximately 5 meters long and 48" dia. Last reported position Lat 24° 22.680 N - Long 053° 25.100E.

The tanks are unlit and may pose a hazard to the vessels navigating around the area.

Mariners are requested to Keep clear and navigate with caution in this area.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END OF TEXT WARNING

Col: 127/2016, 25, 2016, 3178, 2889, 2837, 2858, 5, 48, 24, 22.680, 053, 25.100

MENAS is an ISO 9001:2008 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: ++973 17828541 Fax: ++973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org