



# MIDDLE EAST NAVIGATION AIDS SERVICE NOTICE TO MARINERS

## NOTICE TO MARINERS

NTM: 14/2024

ISSUED DATE: 29<sup>th</sup> December 2024

### Central Gulf: Bahrain– Buoy Altered in Position.

BA Chart: 3736

BH Chart: 1501

MSI-2 Buoy has been altered in position 26-11.675N, 050-36.675E

Mariners are requested to update their BA charts.

**Issuer: MENAS Maritime Operations Centre, Bahrain  
Megulite**

Mariners are requested to inform the Middle East Navigation Aids Service, P. O. Box 66, Manama, Bahrain immediately on the discovery of new dangers, or suspected dangers to navigation and changes or defects in aids to navigation noticed in Sub-Navarea IX - Gulf and its Approaches.

#### **MENAS is an ISO 9001:2015 Certified Service**

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email [info@menas.com.bh](mailto:info@menas.com.bh)

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at [menas.org](http://menas.org) Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through [menas.org](http://menas.org)

**[www.menas.org](http://www.menas.org)**

