



MIDDLE EAST NAVIGATION AIDS SERVICE NAVTEX WARNING - MENAS BAHRAIN via BAHRAIN RADIO (A9M)

NAVIGATION WARNING TO ALL GULF SHIPPING

NAV NO: 029/2024

DATE: 31st January 2024

S. O. P: TFN.

TEXT OF WARNING

Southern Gulf: Yas & Ruwais Channel – Buoys Temporary Altered in Position.

BA Chart: 3780, 3179.

Buoys at Yas & Ruwais channel are temporary altered in position as listed below:

Yas 3	24-20.808N	052-40.144E
Yas 4	24-20.887N	052-40.312E
Yas 4-A	24-20.197N	052-40.431E
Yas 5	24-19.491N	052-40.373E
Yas 6	24-19.507N	052-40.550E

Mariners are requested to navigate with caution and update their BA chart.

**Issuer: MENAS Maritime Operations Centre, Bahrain
Megulite**

END OF TEXT WARNING

Col: 029/2024, 31, 2024, 3780, 3719, 3, 24-20.808, 052, 40.144, 4, 24, 20.887, 052, 40.312, 4, 24, 20.197, 052, 40.431, 5, 24, 19.491, 052, 40.373, 6, 24, 19.507, 052, 40.550.

MENAS is an ISO 9001:2015 Certified Service

All MENAS service users are requested to pass on valid navigational hazard information to the MENAS MARITIME OPERATIONS CENTRE in Bahrain using communications methods:

Tel: +973 17828541 Fax: +973 17727765 Email info@menas.com.bh

MENAS is committed to maritime safety in the region and MENAS support the standards of marine operations recommended by IMCA, the International Marine Contractors Association.

As part of our process of continual improvement of services to the maritime community, we are continually amending / updating our mailing lists. Please reply to this mail address should you require any additional email addresses added to the direct NAVTEX and/or Gulf Notices to Mariners circulation lists.

Please also find latest navigational situation information at menas.org Users are requested to provide suggestions for Service enhancements, navigational hazard feedback and complaints through menas.org

www.menas.org